


**ANACONDA Copper Company**

New Mexico Operations  
P.O. Box 638  
Grants, New Mexico 87020  
505/876-2211



U.S. GEOLOGICAL SURVEY  
ALBUQUERQUE, NEW MEXICO

January 25, 1980

Area Mining Supervisor  
UNITED STATES DEPARTMENT OF INTERIOR  
GEOLOGICAL SURVEY  
P. O. Box 26124  
Albuquerque, New Mexico  
87125

Re: P-7/P-10 Underground Mine  
Report - Fourth Quarter, 1979

Dear Sir:

In accordance with your approval of the incorporation of the P-7 area into the the P-10 underground mine, we are sending you the following data:

1. Fourth Quarter 1979 Resurvey, Report of Subsidence Survey, Jackpile Mine.
2. Bacterial Water Reports for the P-10 Mine Well and the New Shop Well for the Fourth Quarter of 1979.  
  
Chemical and Radiological Analysis of the P-10 Mine Well and the New Shop Well for the Fourth Quarter of 1979.

3. Gallons of Water Pumped from the P-10 Mine Well and the New Shop Well during the Fourth Quarter of 1979.

Gallons of Water Discharged from the P-10 Mine during the Fourth Quarter of 1979.

Sincerely,

Meade A Stirland  
Manager, Environment, Health & Safety

MAS/bg

Encls.